## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

		SECURITY INFORMATION			· .	25) 
DUNTRY	USSR (Kaliningrad Obl	Last)	REPORT			
BJECT	Torpedo Shop in Kalin	ningrad	DATE DISTR.	13 M	ay 1953	
			NO. OF PA	GES & 4		
TE OF INFO	).		REQUIREMENT	T NO. RD		0.5
ACE ACQUIR	ED		REFERENCES			25)
	This is UNEVALUATED I	Information			. ,	
		VALUATIONS IN THIS REPO PRAISAL OF CONTENT IS (FOR KEY SEE REVERSE	TENTATIVE.		2	25 <b>&gt;</b>
Loca	ation					
betv km e	torpedo shop near Kalini ween the Pregel River and east of the railroad stat 1, Page 3.)	d the railroad l:	ine from Primor	sk: (N54-44, E20	<b>–01),a</b> bout <b>t</b>	wo h
Hist	ory					2
Proc 3. Torp	duction Dedoes of various types a Embled after replacement					~.) y
						25
Pers	sonnel					
4. The were	officer in command of the 600 workers, including luding 15 to 20 soldiers.  was done in two shifts	100 Germans and 3 In July 1951 a	30 to 50 Mongol all the Germans	s; the rest were were replaced l	e Soviets.	
4. The were	officer in command of the 600 workers, including luding 15 to 20 soldiers. was done in two shifts	100 Germans and 3 In July 1951 a	30 to 50 Mongol all the Germans	s; the rest were were replaced l	e Soviets.	
4. The were included work	officer in command of the 600 workers, including luding 15 to 20 soldiers. was done in two shifts	100 Germans and 3 In July 1951 a with about 300 with about 300 with a bout 300 with a bout 300 with a bown with a	30 to 50 Mongol all the Germans workers in each was too weak, t	s; the rest were were replaced l shift. he shop had two	e Soviets.	
4. The were incl Work  Power  5. As the engineers	officer in command of the 600 workers, including lading 15 to 20 soldiers. was done in two shifts are	100 Germans and 3 In July 1951 a with about 300 with about 300 with a bout 300 with a bout 300 with a bown with a	30 to 50 Mongol all the Germans workers in each was too weak, t	s; the rest were were replaced l shift. he shop had two	e Soviets.	
4. The were incl Work  Fowe  5. As t engi  Oris  6. Spar	officer in command of the 600 workers, including lading 15 to 20 soldiers. was done in two shifts the electric power suppliance of its own to provide	100 Germans and 3 . In July 1951 a with about 300 with about 300 with about 300 with about 300 with a town with a power for light	30 to 50 Mongol all the Germans workers in each was too weak, t hting and machi	s; the rest were were replaced l shift. he shop had two nery.	e Sovieta, by Sovieta	
4. The were incl Work  Fowe  5. As t engi  Oris  6. Spar	officer in command of the 600 workers, including lading 15 to 20 soldiers. was done in two shifts the electric power suppliances of its own to provide the of Raw Material reparts were brought maishop.	100 Germans and 3 . In July 1951 a with about 300 with about 300 with about 300 with about 300 with a town with a power for light	30 to 50 Mongol all the Germans workers in each was too weak, thing and machine to occasionally	s; the rest were were replaced is shift.  he shop had two nery.  by rail, to the i	e Sovieta, by Sovieta	

25 YEAR **RE-REVIEW** 

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)

22.2 69/ Approved For Release 2009/02/12 : CIA-RDP80-00810A000400540003-8

	SECRET/CONTROL - U. S. OFFICIALS ONLY 25X1
	2 -
٠	Destination of Completed Torpedoes
7.	The overhauled torpedoes were generally taken directly from the shop by small freighters  very rarely they were shipped by rail.
	Security Measures
•	The shop was surrounded by a barbed-wire fence about two meters high. There were no watchtowers. Inside the shop there was a Soviet military guard, about 15 to 20 strong, with red tabs but no numbers on their shoulder boards. When the entrances were open, they were guarded by single sentries armed with rifles. All entrances were seldom open at the same time.
	Union Foundry
).	About two km southwest of the torpedo shop, on the south bank of the Pregel, is another Soviet undertaking the Union Foundry (No. 2 on Sketch No. 1).


25X1


harbor mines were made there.

SECRET/CONTROL - U. S. OFFICIALS ONLY

3 -


25X1





## Sketch # 2.

Detailed Layout of Corpedo Shop



SECRET/CONTROL - U. 8.	OFFICIALS ONLY	25X

## Key to Sketch No. 2

- A. Grounds of a former factory about 300 x 200 m.
- B. Grounds of a former factory about 150  $\times$  100 m.

Some of the buildings are of brick; these include repaired buildings. Others are newly-built from rubble. The buildings are in a bad state and the work is rough. The roofs are of pantiles.

- Building, about 40 m long x 20 m wide. The north part is a hall and the south part
  is a house with two rows of windows in which are quartered the guard and some
  offices. The torpedoes, which arrive in a very dirty and battered condition, are
  rough-cleaned in the hall.
- 2. Hall, about 60 m long, in which torpedoes are dismantled and their parts are cleaned.
- Hall, about 80 x 30 m. South part (broken line on sketch) destroyed, Assembly of torpedoes and fitting of new parts.
- 4. Hall, about 35 x 15 m, used for inspection of overhauled torpedoes.
- 5. Hall, about 35  $\times$  15 m, used for repair of old parts and fitting of new parts.
- 6. Power station.
- 7. Hut, about 25 x 10 m., occupied by the management.
- 8. Shed, about 35 x 20 m, for storage of torpedoes before and after overhauls. The area north of the shed contained a dump of totally unserviceable torpedoes and torpedo scrap.
- 9. Guard house on the island facing the shop.

  All ships and boats intending to berth off the shop had to report here.
- 10. A motor boat, always stationed here to control arriving vessels.

25X1

SECRET/CONTROL - U. S. OFFICIALS ONLY